Outlook

**Bridge Advertisement (DSI 26-016) Brushed-on zinc paint repair option**

**From** Debra M. Butchart <Debra.Butchart@modot.mo.gov>
**Date** Tue 10/27/2026 8:45 AM
**To** BR <BR@modot.mo.gov>

The Missouri Standard Specifications have been updated as described below:

**Implementation Statement:** Effective immediately for all jobs even if submitted to Design or under contract.

*(The Implementation Statement is a recommendation by the Development Section. The SPM is responsible for the level of implementation for any particular job.)*

| Revision Date | Items Revised | Description of Change |
|---|---|---|
| Oct. 2026 | EPG:<br>NA | Sec 1081 updated to allow brushed-on zinc paint option for galvanized coating repair for steel and miscellaneous metals with approval of the engineer. Paints containing zinc dust shall be applied in two coats and shall leave a minimum of ninety-three (93) percent pure zinc in a dry film. Methods using zinc sprays (aerosols) will not be permitted on any repairs. |
| | Bridge Standard Drawings:<br>NA | |
| | MicroStation Cells:<br>NA | |
| | Std. Specifications:<br>1081 | |
| | Standard Plans:<br>NA | |
| | Bridge Special Provisions:<br>NA | |

Follow links above for more information (internal only).

Debra M. (Debbie) Butchart
Structural Specialist
Development Section
Bridge Division
MoDOT- 105 West Capitol Ave
573-522-8718