

- ① Use note H3.29.1 with Grade 50W steel.
Use note H3.29.2 when steel superstructure is galvanized.
(H3.29 shown)
- ② Remove underlined portion when steel superstructure is galvanized.
- ③ Remove these notes if PTFE surface is flat.