

From: [Debra M. Butchart](#)
To: [BR](#)
Subject: Bridge Advertisement (DSI 24-005) Galvanized Reinforcing Steel
Date: Monday, June 17, 2024 9:13:50 AM

The [EPG & Bridge Standard Drawings](#) have been updated as described below:

Implementation Statement: Effective immediately for all jobs even if submitted to Design or under contract.

(The Implementation Statement is a recommendation by the Development Section. The SPM is responsible for the level of implementation for any particular job.)

Revision Date	Items Revised	Description of Change
June 2024	EPG: 751.50 (C1.20)	Several recent galvanized reinforcing steel projects experienced bubbling after the deck was poured.
	Bridge Standard Drawings: BILL01 <i>(Effective date not changed. Revision of alternate details only.)</i>	After an investigation it is believed that the cut ends were being treated with a product that contains significant amounts of aluminum. A standard note (C1.20) has been added to EPG 751.50 (and Bridge Standard Drawing BILL01) stating that damaged zinc coating shall not be repaired with products that contain aluminum.
	MicroStation Cells: NA	The note was also added to the Barbill Program output, below the totals table for galvanized steel.
	Std. Specifications: NA	
	Standard Plans: NA	
	Bridge Special Provisions: NA	

Follow links above for more information, or to view more details about this (or any) revision, use the [Revision Index Database](#), located under Completed Revisions on Development's Sharepoint page.

Instructions:

Under Tables (left-hand side) double-click on RevisionRecords.

Click on the link under the Effective Date to access documentation for the completed revision.

Debra (Debbie) Butchart

(formerly Debra Beckwith)

Structural Specialist

Development Section

Bridge Division

MoDOT- 105 West Capitol Ave

573-522-8718

