

Overlay Components

- ***Nominal Depth Milling Only***
 - Example (1" Depth Following Existing Ground)

Overlay/Stripping Properties

Top option:	Follow Surface	Alternate Bottom Surface:	
Bottom option:	Follow Surface		
Component Depth:	0.0000	Label:	Component Depth
Surface:	<Active>	<input checked="" type="checkbox"/>	Stripping Component
Surface Depth:	0.0833	Label:	Surface Depth

Depth Measured from
Active Surface – **Ignores Profile**

Top Option = Follow Surface
Bottom Option = Follow Surface
Component Depth = 0.0
Surface Depth = +0.083

